

RECEIVED
CENTRAL FAX CENTER
MAY 22 2008

IN THE SPECIFICATION:

Please replace the second paragraph, starting on line 6 on page 10, with the following amended paragraph as follows:

Evaluation was carried out on the generation of cracks in the bending processed portions when the bending processed portions were formed by the compression molding of the support (insulating bases) coated respectively with dielectric materials respectively having the glass transition temperatures of 85, 67, 45, 40, 35, 25, 5, [[1]] 2, -20 and -29°C.